



**PRODUCT RECALL: Dynamite Prophet Sport II
AC/DC Peak Chargers (DYN4077) Sold In Canada**



June 4, 2013

Product: Dynamite Prophet Sport II AC/DC Peak Charger (DYN4077)

Defect Issue: This product recall addresses the Prophet Sport II AC/DC Peak Charger. This charger has not been evaluated for any Canadian Standards and does not bear any recognized certification mark. Horizon Hobby is recalling this product from the Canadian marketplace.

What To Do: Return the product to Horizon Hobby by following the process detailed under Corrective Action below. Consumers following the process will receive a check in the amount of \$29.99 USD approximately 14–21 days after the charger is returned. Retailers returning this product will receive a credit for the dealer NET.

Corrective Action

1.
 - o Please complete the electronic Return Request form [by clicking here](http://www.dynamiterc.com/ProdInfo/Files/DYN077_Return_Request_Form.pdf) or pasting this link (http://www.dynamiterc.com/ProdInfo/Files/DYN077_Return_Request_Form.pdf) into your browser.
 - o Upon receipt of the completed form, a prepaid shipping label will be sent to you via email. If no email address is provided on the Return Request form, the shipping label will be mailed to you. Return your charger, along with a printed copy of the completed Return Request form. Upon receipt of the product, Horizon Hobby will issue a check in the amount of \$29.99 USD. Please allow 14–21 days for processing and delivery.

We apologize for this inconvenience. Horizon disclaims all liability and warranties for any consumer failing to act upon this product recall.

Horizon Hobby	Contact Information	Address
Horizon Service Center (Repairs and Repair Requests)	https://www.horizonhobby.com/content/_service-center_render-service-center	4105 Fieldstone Rd Champaign, Illinois, 61822 USA
Horizon Product Support (Product Technical Assistance)	http://www.quickbase.com/db/bghj7ey8c?a=GenNewRecord 877-504-0233	
Sales	sales@horizonhobby.com 888-959-2306	